
## piececool






It is recommended to use piececool authentic assembly tools to build or fix the design. It is tailor made for the metal pieces and user friendly.

WARNING – Please handle metal sheets with care. The parts may have sharp edges that could cut or scratch skin. Keep away from children.

c. Folding the parts


**Folding Metal** 

## • Installation Method:




Please use the clipper to cut the nozzle position and remove the parts.

d. Retaining the parts




Insert the hole, bending tab with angle 90°

## b. Identify the parts



Identify the insert tab, fold line and the insert hole.



Insert the hole, twisting tab with angle 90°

Attention:

Engraved / Color side


NE Non-engraved / Silver side


Attention Point


Keep the parts symmetrical


When cutting metal parts, please do not cut the "insert tab" as "nozzle position". Only cut the parts of the current step when cutting the parts. Do not cut all the parts at one time to avoid loss.


When encountering the parts of the folding line, please pay attention to the front and back of the metal sheet and the direction of the folding. According to the direction indicated in the instruction, cut lightly and fold slowly. It is best to fold it once. Do not fold it repeatedly to avoid damage to the parts.












































Curve the band manually

Fold the RED part forwards

B -45 <----

AB

