
piececool




Engraved / Color side

Attention Point

(NE) Non-engraved / Silver side

Keep the parts symmetrical



When cutting metal parts, please do not cut the "insert tab" as "nozzle

position". Only cut the parts of the current step when cutting the parts.

When encountering the parts of the folding line, please pay attention to the

front and back of the metal sheet and the direction of the folding. According

to the direction indicated in the instruction, cut lightly and fold slowly. It is best

to fold it once. Do not fold it repeatedly to avoid damage to the parts.

Do not cut all the parts at one time to avoid loss.

